



**HAGGLUNDS BV206
SPARE PARTS CATALOG**



Price and availability subject to change without prior notice due to sales, inventory shortages, and/or unforeseen economic circumstances.



Rubber Track 620*90.6*64

Material: Rubber + KEVLAR

Weight: ~440 lbs

OEM: 253 6122-801

NSN: 2530-01-166-1971

Warranty: 1 year

Price: \$3,500.00



Transmission Shaft

P/N: TS001

OEM: 253 6064-801

Price: \$1,350.00



Drive Shaft Assembly

P/N: DS002

OEM: 253 6358-801

Price: \$1,050.00



Universal Joint (Complete Assembly)

P/N: CSD006

OEM: 353 7142-804

Price: \$685.00

Price and availability subject to change without prior notice due to sales, inventory shortages, and/or unforeseen economic circumstances.



Cardan Shaft

P/N: CSG002

OEM: 253 6063-801

Price: \$1,060.00



Damping Cylinder

P/N: DC022

OEM: 353 6264-801

Price: \$990.00



Steering Cylinder

P/N: SC023

OEM: 253 6222-801

Price: \$1,050.00




Transfer Case

HÄGGO NR: 153 6085-804

Rebuilt: Yes

Price: Call for Pricing & Availability

Price and availability subject to change without prior notice due to sales, inventory shortages, and/or unforeseen economic circumstances.



Final Gear Unit

HÄGGO NR: 153 6140-805

Rebuilt: Yes

Price: Call for Pricing & Availability



Support Wheel Arm

P/N: SWA005

OEM: 353 6136-801

Price: \$300.00



Drive Sprocket Fixing Bolt (With Washer)

P/N: FB015

OEM: 2121 2032-697

Price: \$40.00



Drive Sprocket

OEM: 253 6116-801, 3020-01-163-4970

Price: \$470.00

Price and availability subject to change without prior notice due to sales, inventory shortages, and/or unforeseen economic circumstances.



Hollow Shaft Spline Drive System

P/N: HSS013

OEM: 253 6708-001

Price: \$450.00



Large Sleeve for Drive System

P/N: LS014

OEM: 353 6120-001

Price: \$175.00



Drive Sprocket Bearing Kit

P/N: DSBK015

OEM: 253 6115-802

Price: \$325.00



Drive Sprocket Fixing Bolts

P/N: FB005

OEM: 2121 2032-697

Price: \$25.00

Price and availability subject to change without prior notice due to sales, inventory shortages, and/or unforeseen economic circumstances.



Drive Sprocket Fixing Bolt Washer

P/N: FW005

OEM: 453 6165-001

Price: \$13.00



Swing Arm

P/N: SA008

OEM: 253 6120-801, 253 7070-804, 2530-01-275-7482, 2 0008-217, 3 0008-218

Price: \$562.00



Swing Arm Fixing Bolt

P/N: FB004

OEM: 453 6187-001

Price: \$25.00



Road Wheel Fixing Bolt & Washer

P/N: FB012

OEM: 2121 2541-501 (Bolt)
453 6522-001 (Washer)

Price: \$9.00

Price and availability subject to change without prior notice due to sales, inventory shortages, and/or unforeseen economic circumstances.



Dust Cover (Road Wheel)

P/N: DC001

OEM: 453 6189-801

Price: \$10.00



Support Wheel

Item No: TTG SW004

OEM: 453 6197-802, 453 6197-801

Price: \$380.00



Road Wheel

OEM: 353 6103-801

Price: \$325.00



Road Wheel Assembly with Bearing Kit

OEM: 353 6126-803

Price: \$380.00

Price and availability subject to change without prior notice due to sales, inventory shortages, and/or unforeseen economic circumstances.



Road & Support Wheel Bearing Kit

Includes: 2 Bearings, 2 Seals, 1 Cap, 1 Sleeve
P/N: BKS002

OEM: 353 6103-801
Price: \$70.00



Wear Ring for Road Wheel

P/N: GR009

OEM: 353 6678-001
Price: \$11.00



Seal Ring for Road Wheel

P/N: SR001

OEM: 353 6189-801
Price: \$10.00



Single Row Radial Ball Bearing (Large) FAG

P/N: BB6206
Material: Bearing Steel
OEM: 2213 2141-050
Price: \$15.00

Price and availability subject to change without prior notice due to sales, inventory shortages, and/or unforeseen economic circumstances.



Single Row Radial Ball Bearing (Small) FAG

P/N: BB6205
Material: Bearing Steel
OEM: 2213 2141-050
Price: \$14.00



Reparation Kit for Steering Unit

P/N: SURK037
OEM: 1536 6764-804
Price: \$1,145.00



Pivo Bearing for Steering Cylinder

P/N: SUP035
OEM: 2184 4221-060, 153 6174-803 (Repair Kit)
Price: \$190.00



Pivo Bearing for Steering Unit

P/N: SUP034
OEM: 2184 4234-070
Price: \$106.00

Price and availability subject to change without prior notice due to sales, inventory shortages, and/or unforeseen economic circumstances.



Bearing Kit for Steering Unit

P/N: BSU036

Price: \$520.00



Coover

P/N: SUC031

OEM: 353 6843-801, 2 0003-856

Price: \$420.00



Sleeve

P/N: SUC032

OEM: 453 7194-001

Price: \$70.00



Steering Unit Bolt

P/N: SUB033

OEM: 453 6364-001, 2 0005-823

Price: \$70.00

Price and availability subject to change without prior notice due to sales, inventory shortages, and/or unforeseen economic circumstances.



Tension Unit Track Tensioner

P/N: TU024

OEM: 153 6107-801, 2 0001-066

Price: \$1,375.00



Tension Unit Fixing Screws

P/N: TFS011

OEM: 453 6171-001

Price: \$68.00



Tension Frame Bushing / Frame Wear Ring

P/N: TFB018

OEM: 453 6173-001, 453 7360-001

Price: \$75.00



Steering Unit Sealing Rubber

P/N: SUR003

OEM: 353 6301-001

Price: \$60.00

Price and availability subject to change without prior notice due to sales, inventory shortages, and/or unforeseen economic circumstances.



Steering Cylinder Pin

P/N: SCP002

OEM: 453 6372-001

Price: \$70.00




Tension Unit Repair Kit

P/N: TUR021

OEM: 453 6170-001, 453 7360-001, 453 7637-001,
2126 2532-124

Price: \$230.00



Torsion Spring

20 pcs needed for BV206

OEM: 2530-01-167-2021, 253 6114-801

Price: \$475.00



Axle Coupling for BV206 Diesel Engines

P/N: CSD005

OEM: 535 7142-601

Price: \$137.00

Price and availability subject to change without prior notice due to sales, inventory shortages, and/or unforeseen economic circumstances.



**Rubber Bellows, Transfer Box
(Transmission Gator)**

P/N: RB001

OEM: 153 6081-001, 5342-01-168-1467

Price: \$160.00



Piston for Brake Caliper

P/N: PBC03

Price: \$59.00



Reparation Kit for Brake Caliper

P/N: RKBC01

OEM: 153 6087-610

Price: \$43.00



Piston for Brake Caliper

P/N: PBC02

Price: \$59.00

Price and availability subject to change without prior notice due to sales, inventory shortages, and/or unforeseen economic circumstances.



Brake Caliper (Left)

P/N: BC001

OEM: 153 6087-003, 2530-01-171-8395

Price: \$460.00



Brake Caliper (Right)

P/N: BC002

OEM: 153 6087-804, 2530-01-171-8395

Price: \$460.00



Connection Sleeve

P/N: CS001

OEM: 2 0000-321

Price: \$598.00



Adapter

P/N: AS002

OEM: 253 6457-001

Price: \$598.00

Price and availability subject to change without prior notice due to sales, inventory shortages, and/or unforeseen economic circumstances.



Intermediate Shaft

P/N: ISH001

OEM: 153 6091-801

Price: \$1,300.00



Radiator Lock

OEM: 6932 4951-120

Price: \$40.00



Brake Disc

Material: Weldox700

OEM: 253 6073-002

Price: \$760.00



Water Valve

P/N: WAV001

OEM: 353 6382-801

Price: \$60.00

Price and availability subject to change without prior notice due to sales, inventory shortages, and/or unforeseen economic circumstances.



Fuel Pump Ford V6

P/N: FP002

OEM: 453 7091-006


Price: \$146.00



Brake Pads

OEM: 453 6064-802

Price: \$50.00



Master Brake Cylinder

P/N: MBC001

OEM: 153 6308-801, 2530-01-167-1799

Price: \$665.00




**Service Kit for Master Brake Cylinder
(New Kit for MBC001 ←)**

OEM: 153 6082-606, 2530-99-763-4947


Price: \$160.00

Price and availability subject to change without prior notice due to sales, inventory shortages, and/or unforeseen economic circumstances.



[Stop Light Switch](#)

OEM: 5663 4133-70
Price: \$40.00



[Brake Switch \(Parking Brake\)](#)

OEM: 5663 4139-211
Price: \$34.00



[Parking Brake Wire](#)

OEM: 353 6049-801
Price: \$362.00



[Wiper Motor](#)

For Haggglunds BV206 2-Speed
Price: \$290.00

Price and availability subject to change without prior notice due to sales, inventory shortages, and/or unforeseen economic circumstances.



Hinge Tee

OEM: 453 6129-801
Price: \$150.00



Ignition Lock (Diesel)

Price: \$121.00



Throttle Linkage Gas Wire

Cable – Control Assembly

OEM: 453 6228-801
Price: \$285.00



Tahometer 24v Diesel

Signal from Alternator "W"

Price: \$230.00

Price and availability subject to change without prior notice due to sales, inventory shortages, and/or unforeseen economic circumstances.



Head Lamp, KPL 45w, IP68, 9-36v, LED

Certification: E-mark

P/N: HL001

OEM: 5921 2048-024

Price: \$300.00 (ea), Mounting Set Included



Hydraulic Oil Filter

OEM: 2590 4161-601

Price: \$103.00



Radiator

For BV206 D6 (Diesel 6 Cylinder, BV206 V6 (Petrol 6 Cylinder

P/N: RD001

OEM: 453 8940-801

Price: Call for pricing & availability

Price and availability subject to change without prior notice due to sales, inventory shortages, and/or unforeseen economic circumstances.



Water Pump Ford V6

OEM: 453 7091-093

Price: \$214.00




Heater Fan Front Cab 24v

P/N: EFF001

OEM: 153 6150-647

Price: \$366.00, Mounting Kit Included



Heater Fan Rear Cab 24v

P/N: EFR002

OEM: 153 6050-801, 253 6498-801, 453 6803-801

Price: \$277.00, Mounting Kit Included



Fuel Filter

P/N: FF003

Price: \$122.00

Price and availability subject to change without prior notice due to sales, inventory shortages, and/or unforeseen economic circumstances.



Engine Mounting OM603

P/N: EM002

Price: \$100.00



Alternator 24v, 90A

OEM: 253 6204-801, 353 6809-801, BOSCH 0120468066

Price: \$530.00



Starter for BV206 D6 (Diesel 6 Cylinder)

P/N: DS004

OEM: 453 7796-803

Price: \$685.00




Door Rubber Sealing

Quantity Needed for BV206: ~ 85ft

OEM: 453 9041-001


Price: Call for Price & Availability

Price and availability subject to change without prior notice due to sales, inventory shortages, and/or unforeseen economic circumstances.



Hydraulic Pump

OEM: 253 6041-803
Price: \$1,740.00



Full Engine Gasket Set (Ford 2.8 V6)

Price: \$395.00



Replacement Carburetor

Weber for Ford V6 Petrol

Price: \$1,039.00



Solex Carburetor Repair Kit

OEM: 453 7091-066
Price: \$137.00

Price and availability subject to change without prior notice due to sales, inventory shortages, and/or unforeseen economic circumstances.



Weber Carburetor Repair Kit

Price: \$137.00



Distributor Lock

P/N: DL001

OEM: 3569 4121-606

Price: \$60.00



Ignition Cable Kit

P/N: ICK001

OEM: 353 6007-801, 801-806, 453 6012-801

Price: \$270.00



External Water Pump

P/N: EWP004

OEM: 4320-99-763-4909

Price: \$670.00

Price and availability subject to change without prior notice due to sales, inventory shortages, and/or unforeseen economic circumstances.



Windshield Washer Pump

P/N: FGH001

OEM: 6179 2141-024, 2540-21-898-2463

Price: \$85.00



Fuel Tank Rubber

OEM: 453 7106-981

Price: \$55.00 per ft




Fan Motor Front

OEM: 153 6150-624

Price: \$215.00

Price and availability subject to change without prior notice due to sales, inventory shortages, and/or unforeseen economic circumstances.




Fan Motor Rear

OEM: 253 6189-601
Price: \$165.00



Ignition Coil 24v

OEM: 3569 4111-024
Price: \$185.00



Front Heater Core

HAGGO NR: 5855-01-388-4332
Price: \$475.00



Rear Heater Core

OEM: 253 6189-602
Price: \$350.00

